

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 128177

RECEIVED FROM Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080114-7

DATE REC'D 1-22-59

P. O. NO. 69204

VENDOR PACKING SLIP NO. 11756

ACCT. OR R. W. O. NO.

S. O. NO.

CHARGE TO

322

QUANTITY RECEIVED

DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	REMARKS	QUANTITY	ACCEPTED	REJECTED
								REMARKS	ACCEPTED	REJECTED
322 000000 10161	COUPLING - 50Z	730163-97						10		

RECEIVED BY

INSPECTED BY

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 128186

RECEIVED FROM

DATE REC'D 1-22-59

P. O. NO.

VENDOR PACKING SLIP NO.

ACCT. OR R. W. O. NO.

S. O. NO.

CHARGE TO

322

QUANTITY RECEIVED

DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	REMARKS	QUANTITY	ACCEPTED	REJECTED
								REMARKS	ACCEPTED	REJECTED
322 000000 10161	COUPLING ASSY							25		

INSPECTED BY

Dua DATE 1-22-59

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVED BY

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080114-7